



Troubleshooting Guide



Table of Content


I:	License / Registration	3
II:	Vista: Repeat Registration Problem – Trial Mode	4
III:	Sensor Capture Error – Suni hardware could not be found	6
	64 Bit Operating System Support	9
IV:	Abort Sensor in Middle of Layout Series.....	10
V:	Sensor Self Triggering	11
VI:	Sensor Not Triggering	13
VII:	ProfSuni Software Upgrade Error	14
VIII:	Out of PAC License Warning	15
IX:	Image Quality – Grainy (or “noisy”)	16
X:	Image Quality – Dark (or “burned out”)	19
XI:	Image Quality – Stripes on the Edge (or “stair-stepping”).....	20
XII:	Image Quality – Blurry (or “fuzzy”)	22
XIII:	XVA Crash in Middle of Layout Series	24

I: Licensing / Registration

After launching ProfSuni from the icon onto your desktop, you will see the following: Trial Version Licensing Information screen.



Click on the **Register** button to get to the next screen:



Enter the license 9C50-685A-****, user name information, skip STEP 2: ACTIVATION CODE and click on **DONE** to get into the program.

II: Vista: Repeat Registration Problem – Trial Mode

Symptoms:

After registering the software in Vista, and re-launches the program, it asks for registration information again.

Register

Prof. Suni

STEP 1: REGISTRATION INFORMATION

Please enter the following information in order to register this product. Your registration number can be found on either a registration card or on a label located on the CD-ROM sleeve.

Registration Number:

I have additional registration numbers I would like to use

Install ID:

User Name:

User Company:

User Email:

User Phone:

STEP 2: ACTIVATION CODE


You may obtain your Activation Code by clicking on the "Get Activation Code" button or by visiting <http://apteryx.com/register>; both options require internet access. You may also call your Sales Representative or Apteryx Technical Support during business hours.

STEP 3: CONTINUE

If you do not have an internet connection, you may simply press the "Done" button.

Solution:

The problem occurs because the user does not have the administrative privileges necessary to create registration information. To properly register the software, the user should right click on **ProfSuni.exe** and choose **'Run as administrator'**.




Re-enter the registration number 9C50-685A-****, user information and skip STEP 2: ACTIVATION CODE, then click **DONE** to access the program.

III: Sensor Capture Error – Suni hardware could not be found!

Problem:

After positioning the sensor and activating the unit, the following message is displayed.



This error message is generated due to one of the following situations:


- a) The Suniray USB is not recognized by the computer
- b) The Suniray USB driver is not installed
- c) Insufficient power from the computer USB port
- d) The Suniray USB firmware files need to be updated

Solution:

- a) The Suniray USB is not recognized by the computer
 - Make sure the Suniray sensor is plugged in to the back USB port and the computer recognized the hardware.
 - Check the Windows Device Manager to verify if the USB driver was installed successfully.




- If the Suniray USB driver was NOT properly installed, a device named **USB device** marked with a yellow exclamation mark will appear under **other devices**.



b) The Suniray USB driver is not installed

- Insert the ProfSuni disc in the CD-ROM drive. //The driver is in <D:\Drivers\SDR303>
- Double click on **USB Device** in **Other devices** then follow the 'Found New Hardware' wizard to install the driver.




- Follow the prompts to finish the driver installation, when it's done successfully, Digital Radiography Device (SDR303) should be listed under Device Manager.

c) Suniray sensor is not properly plugged in

- Unplug the sensor and re-plug it back in, make sure the connector pushes all the way in.

d) Suniray USB firmware files not updated

- Right click on ProfSuni.exe icon on desktop, select Properties→Find Target and make sure the SuniUSBII.SED file is dated 6/10/09 or newer.



File Name	Size	Type	Date Modified
settings.xml	2 KB	XML Document	5/27/2009 12:07 PM
ssiAdvancedImaging.IADLL	148 KB	IADLL File	2/29/2008 2:06 PM
ssiaip.dll	204 KB	Application Extension	2/1/2008 7:09 PM
Suni Imaging.SED	340 KB	SED File	2/7/2008 12:25 PM
suniusb.dll	108 KB	Application Extension	12/14/2007 6:11 PM
SuniUSB.SED	344 KB	SED File	2/9/2007 10:36 AM
SuniUSBII.SED	724 KB	SED File	6/10/2009 12:47 PM
U12bin021108.mcs	85 KB	MCS File	12/10/2002 10:16 AM
U12std021108.mcs	85 KB	MCS File	12/10/2002 10:16 AM


- Go to http://www.apteryxware.com/dental/downloads/xva3_5/suni.shtml for the latest SuniUSBII firmware upgrader.

Note: Suni hardware USB2000 and Suniray currently support 64-bit operating system; please refer to the readme.txt file in the TEC_Driver folder in our FTP site for proper installation instructions.

IV: Abort Sensor in Middle of Layout Series

Symptoms:

When trying to switch sensor or stop in the middle of layout capturing, the following message is displayed:



Cause:

User did not quit image captures properly or completed the previous captures before closing it.

Solution:

Finish the image capturing or stop layout series properly by clicking on the red 'X' on the lower bottom left hand corner to abort capturing.

V: Sensor Self Triggering

Problem:

The sensor triggers by itself without any radiation induces.

This problem may occur due to the following:

- a) Sensor enclosure splitting/opening
- b) Sensor cable(internal) or connector damaged
- c) Insufficient power from computer USB port
- d) Noise Interference

Solution:


- a) Sensor enclosure splitting/opening
 - Inspect the enclosure of the sensor and make sure there's no splitting or cracks on the sensor.
- b) Sensor cable(internal) or connector damaged
 - Switch out the sensor. If the new sensor works, the problem most likely to be the first sensor; if the problem persisted, then it might not be the sensor.
- c) Insufficient power from computer USB port
 - Use the Ultra brand powered USB hub came with the sensor, connect the sensor to one of the ports and the cable from the port to the USB port.
- d) Noise Interference
 - Go to **Tools**→**Options**→**SuniUSBII**→**Detection Sensitivity and Threshold**, lower the sensitivity value by 2 until no self-trigger is observed.

Or

- e) Go to **Tools**→**Options**→**SuniUSBII**→**Detection Sensitivity and Threshold**, increase threshold value by 16 until no self-trigger is observed.

(Default is 160)

Password: **dentalimage**



VI: Sensor Not Triggering

Problem:

When attempting to capture an image, screen stays at green 'Sensor Ready' mode even after the radiation induces.

This problem occurs in one of the followings:

- a) Inconsistent or no radiation from the x-ray machine
- b) Sensor not securely connected to the USB cable
- c) Insufficient power from computer USB port
- d) Low Sensor Detection Sensitivity


Solution:

- a) Inconsistent or no radiation from the x-ray machine
 - Increase the exposure settings or change to another x-ray machine to see if the problem persisted.
- b) Sensor not securely connected to the USB cable
 - Unplug the sensor and re-plug it back in, make sure the connector pushes all the way in.
- c) Insufficient power from computer USB port
 - Use the Ultra brand powered USB hub came with the sensor, connect the sensor to one of the ports and the cable from the port to the USB port.
- d) Low Sensor Detection Sensitivity
 - Go to **Tools**→**Options**→**Sensor**→**SuniUSBII**→**Detection Sensitivity and Threshold**, increase Detection Sensitivity value by 2 until trigger is observed.
(Default is 7) *password: dentalimage*

VII: ProfSuni Software Upgrade Error

Symptoms:

After downloading the software upgrader and trying to run it, the following message is displayed:



Resolution:

Make sure ProfSuni program is closed in all computers (local and network) before running the software upgrader.

VIII: Out of PAC License Warning

Symptoms:

When starting ProfSuni, licensing warning information is displayed.



Cause:

The user has used/exceeded the number of licenses were purchased for the software.

Resolution:

To resolve licensing problem, the user must either purchase additional licenses or reallocate previously allocated license by selecting license from the **Licensed Computers** listing and then click on **Reallocate License** button.

IX: Image Quality – Grainy (or “noisy”)

Problem:

Image appears to be too light, grainy and lack of contrast.

Sample grainy image:



Cause:

Grainy (or “noisy”) image generally caused by under exposure.


Solution:

- Increase the exposure setting from the X-ray unit, and/or decrease the distance between the unit and the sensor.
- Use the image enhancement tools – **Brightness and Contrast**. In general, brightness/contrast enhancement changes the brightness and

the contrast of an image in order to try to improve the overall dynamic appearance of an image.

- **Real time B/C** – *This feature can be used to quickly modify the appearance of an image.*

- Open an image, click on B/C on the sidebar to adjust the image by clicking and dragging in the main area of the control. To set the B/C back to normal, you can either double click or right click on the control.



- **Automatic Brightness / Contrast** – *This feature automatically tries to determine the optimal brightness/contrast settings for the image.*
 - Go to **Enhancement**→**Brightness/Contrast**→**Auto Brightness/Contrast** to automatically adjust the brightness and contrast of the image. To set the brightness and contrast back to normal, click on **'Undo All'**.
- **Brightness / Contrast** – *This feature allows you to manually adjust the brightness and contrast of the image. After define the optimal B/C values, and then you can apply them to the pre-filters.*
 - Go to **Enhancement**→**Brightness/Contrast**→**Brightness and Contrast** and enter the optimal B/C values then click OK to save it.

Tips: Presetting Brightness to -5, Contrast to 5 and Gamma to 0.75 usually a good starting point, however, you can increase/decrease the value based on the result of the image.



BC adjustments are used to compensate for radiation variations in your x-ray equipment

Defaults

Posterior

Brightness: -5

Contrast: 5

Gamma Correction:

0.75

Anterior

Brightness: -5

Contrast: 5

Gamma Correction:

0.75

* - password protected options

OK

Cancel

X: Image Quality - Dark (or “burned-out”)

Problem:

Image appears to be too dark, or teeth appear to be jagged.

Sample burned-out image:



Cause:

Dark (or “burned-out) image generally caused by over exposure.

Solution:

Try turning the radiation down a notch. Most sensors operate best at a time of between 0.06 seconds (about 4 pulses) to 0.10 seconds (6 pulses). Usually, a good starting point is at 70kVp, 7mA and 0.06 seconds (about 4 pulses), and then go up or down one notch at a time from there.

Note: It's generally a good idea, though, to get in a habit of having the X-ray unit in the same position of all your X-ray images, this will ensure consistency.

XI: Image Quality - Stripes on the Edge

Problem:

Stripes appear on the edge of the image, or “stair-stepping”.

Sample “stair-stepping” image:




Cause:

Longer warm up pulses from certain AC-head machine.

Solution:

Go to **Tools**→**Options**→**Sensor**→**SuniUSBII**→**Detection and Sensitivity** and then increase the integration time by a step of 50ms until no stripes is observed.




XII: Image Quality – Blurry (or “fuzzy”)

Problem:

Image appears to be blurry, or fuzzy.

Sample “blurry” image:




Cause:

- a) Longer warm up pulses from certain AC-head machine.
- b) Movement from the x-ray head or the image taking technique.

Solution:

- a) Use the same method on page 20 to increase the integration time
- b) Make sure no movement from the x-ray source

Tips: Another way to enhance the blurry image is to use the 'Sharpen' enhancement tool in the application. In Enhancements, go to **Enhancement**→**Sharpen**, then adjust the Sharpening Factor and select the Mask Size to get the optimal result.



The following image as a result of Sharpening Factor set at 20, custom Mask Size of the Width at 41 and Height at 3.



XIII: XVA Crash in Middle of a Layout Series

Problem:

Prof. Suni application crashes in the middle of a layout series.

This problem occurs due to one of the following:

- a) User does not quit or complete active image captures before terminating application.
- b) User capturing image from a layout that previously did not closed.
- c) Computer enters suspend mode.
- d) Bad USB connection to the computer.
- e) Older version of software or USB firmware used.

Solution:

- a) Make sure no capturing in progress before terminating application.
- b) Close the previous progression before capturing under a new one.
- c) Disable the suspend mode of the computer - Control Panel→Power Options
- d) Go to Device Manager and see if the USB driver still recognized. If not, replace the USB cable and/or replace the sensor to see if the problem persisted.
- e) Call Suni technical support at 1-800-GET-SUNI to get help with the appropriate software upgrade.